

FIG. 1




FIG. 2A




FIG. 2B




FIG. 2C

3/27




FIG. 3

SH-0022

2000年11月30日 17時23分

NO. 9044 P. 62/86

09727385 420400

4/27




FIG. 4

SH-0022

2000年11月30日 17時23分

NO. 9044 P. 63/66

5/27




FIG. 5

6/27




FIG. 6




FIG. 7

7/27




FIG. 8

SH-0022

2000年11月30日 17時23分

NO. 9044 P. 66/66







FIG. 9A



**FIG. 9B**



9/27



SH-0022

2000年11月30日 17時23分

NO. 9044 P. 68/66

10/27




FIG. 12




FIG. 13

SH-0022

2000年11月30日 17時23分

NO. 9044 P. 69/66

11/27




FIG. 14

SH-0022

2000#11月30日 17時24分

NO. 9044 P. 70/86

12/27

EXAMPLE 7




FIG. 15

COMPARATIVE EXAMPLE 3




FIG. 16




FIG. 17




FIG. 18A

FIG. 18B




FIG. 19A




FIG. 19B




FIG. 19C




FIG. 20D




FIG. 20C




FIG. 20B






FIG. 20A


NO. 9044 P. 74/86




RELATED ART  
FIG. 21A



RELATED ART  
FIG. 21B




RELATED ART  
FIG. 21C



RELATED ART  
FIG. 21D








FIG. 23



20/27




FIG. 25




FIG. 26

007027386 120100




FIG. 27




FIG. 28




FIG. 29A




FIG. 29B




FIG. 29C




FIG. 30



25/27




FIG. 31




FIG. 32




FIG. 33

0072385-120100




FIG. 34




FIG. 35




FIG. 36

27/27

RESULT OF OPTICAL CHARACTERISTICS

MEASUREMENT ITEMS EXAMPLES	CONNECTING LOSS (dB) IN AVERAGE	ECCENTRICITY (%) IN AVERAGE	TOTAL NUMBER FOR GRINDING
EXAMPLE 13	0.04	0.30	15
COMPARATIVE EXAMPLE 10	0.11	1.06	10


FIG. 37

SH-0022

NO. 9044 P. 66/86

2000年11月30日 17時26分

United States Patent & Trademark Office  
Office of Initial Patent Examination -- Scanning Division



Application deficiencies found during scanning:

☒ Page(s) 6 of 6 of TRANSMITTAL were not present  
for scanning. (Document title)

☐ Page(s) \_\_\_\_\_ of \_\_\_\_\_ were not present  
for scanning. (Document title)

☐ *Scanned copy is best available.*